


Thursday 30th April 2009

I Donald Wallis, purchased a variable speed drive and motor to rotate discs and flywheels, on a large surface grinder. This did not work and the supplier was unable to solve the problem, of the motor stalling. Stephen Peirce, an existing customer, mentioned to me that he was out on his own, as a electrical contractor, specializing in motor control. I immediately asked if he would look at the problem and after 2 days Stephen got back to me with good news. Stephen was confident that we didn't need to replace any equipment and Stephen configured the VSD correctly and rewired the motor. The machine now works perfectly.

Regards



Donald Wallis

Director

- Cylinder
Steering

- Parts &
Service

- Disc & Drum
Machining

- On Car Disc
Machining

- Boosters
Overhauled

- All Mechanical
Repairs

